VEHICLE REPORT

Visual Frame Damage: No General Condition: 2.0

Book Value: 14975

Driveable: Yes

Stock #: 637471

Date: 1/29/16 10:57 AM

Sale Date:

| 1 | 0 | t ‡ | # • |
|---|---|-----|------------|

| Year | Make | | Model | | I I | Body Type | | Doors | | VIN | |
|--------|-----------|------------------|-------|------|---------|----------------|---|-----------|-------------------|------|----------|
| 2009 | CHEVROL | ET | K1500 | | WAG | WAGON 4 DOOR 4 | | 4 | 1GNFK26389R231620 | | 9R231620 |
| Drive | Ext Color | Int Color |]] | nt M | aterial | ЕОТ | L | ic. Plate | State | # of | Expires |
| 4 | Silver | Black | | Cl | oth | | | | | | |
| | Odometer | Eng | ine | | Tran | smission | | Sound | Roof | | Airbags |
| 153657 | Digital | 8 -Cyl. : | 5.3L | F | A | Luto | | w/CD | Hard T | ор | Dual |

- Interior:Power seats, Power windows, Power mirrors, Cruise control, Tilt wheel, Rear air, Rear defroster, Power locks
- Exterior: Alloy wheels, Rear wiper

- **Equipment:**Power steering, Power brakes, Air conditioner, Antilock brake system
- Electronics:Cd player

| Tires: | Left | Right |
|--------|---------------------|---------------------|
| Front | 04/32in Michelin 17 | 04/32in Michelin 17 |
| Rear | 04/32in Michelin 17 | 04/32in Michelin 17 |
| Spare | | |



Announcements:

• AS IS:NO ARB ON FRM

| Inspection Date | Description | |
|-----------------|--|--|
| 01/29/2016 | Front f bumper cover lower missing | |
| 01/29/2016 | Front front emblem missing | |
| 01/29/2016 | Front hood chipped | |
| 01/29/2016 | Lf side If fender dent/no paint dmg | |
| 01/29/2016 | Lr side l qtr panel ding | |
| 01/29/2016 | Overall exterior left overall missing -Moldings | |
| 01/29/2016 | Overall exterior right overall missing -Moldings | |
| 01/29/2016 | Rear rear bumper scratch heavy | |
| 01/29/2016 | Rf side rf door dent/paint dmg | |



Front f bumper cover lower missing



Front front emblem missing



Front hood chipped



Lf side lf fender dent/no paint dmg



Lf side lf tire 04/32in tread



Lr side l qtr panel ding



Lr side lr tire 04/32in tread



Overall exterior left overall missing



Overall exterior right overall missing



Cargo



Front right



Interior



Left side



Odometer



Rear left



Rear right



Right side



Rear rear bumper scratch heavy



Rf side rf door dent/paint dmg



Rf side rf tire 04/32in tread



Rr side rr tire 04/32in tread